SPEEDOL Since 1921 Lubricants



ATF Dexron VI

ATF Dexron VI is a full synthetic red colored automatic transmission fluid formulated with premium synthetic base stocks and advanced additive technology, meets and exceeds the requirements of the DEXRON-VI specification.

Usage

It uses transmissions or hydraulic steering service on which indicates all passengers car DEXRON VI.

Features

High Viscosity Index: The combination of advanced friction modifiers and a high viscosity index fluid ensures smooth, fuel-efficient gear changes and vibration-free torque transfer from the engine to the wheels in all driving conditions.

Low Viscosity Value: Causes lower viscosity drag compared to conventional ATFs.

High Anti-Wear: Improved friction resistance enhances shifting performance.

Excellent Formulation: The exclusive synthetic blend formula surpasses Dexron III-H. Exceptional sludge resistance ensures superior transmission life.

Technical Specifications

*Kinematic Viscosity @100˚C, cSt	ASTM D 445	5,72
*Viscosity Index	ASTM D 2270	163
*Pour Point, °C	ASTM D 97	-42
*Flash Point, °C	ASTM D 92	232

**Data given above are typical properties and may vary slightly.*

Performance

JASO M315 1A-LV	MERCON LV
Acurat ATF-Z1, Aisin Warner JWS 3309 (T-IV) & JWS 3324 (WS), ATF RED 1, RED 1K, AUDI G 055 025 A2 (JWS 3309), BMW JWS 3309(T-IV), BMW Mini, Chrysler Dodge Mopar AS 68 RC (T-IV), JWS 3309, Daihatsu AMMIX ATF D-II, Daihatsu AMMIX ATF D-III SP, FIAT T-IV type, JWS 3309, Ford FNRS, Ford WSS M2C 922A1, 924A (XT-8-QAW) JWS 3309, FUSO ATF-II, FUSO ATF – SP III, FUSO ATF A4, GM 9986195 (Aisin AW, JWS 3309), HINO Blue Ribbon ATF, Honda ATF-Z1 (except in CVTs), Honda DW 1, Hyundai/Kia SP-III, Hyundai/Kia SP IV, Hyundai/Kia SP IV M, Hyundai/Kia SP IV RR, Hyundai/Kia JWS 3314, Hyundai/Kia JWS 9683, ISUZU BESCO ATF-II, ATF-III, JASO M315-2013 1A, JASO M315-2013 1A-LV, JASO M315-2013 2A, Lexus JWS 3309, KIA ATF SP II, SP III, SP IV, SP IVM, Red 1, MAZDA ATF D II, MAZDA ATF M III, Mazda ATF M-V, Mazda ATF FZ,Mazda ATF S- 1,	DEXRON-VI, Ford MERCON, Ford MERCON LV(FF-WSS-M2C-938A/SF, XT-10 QLV), Mazda ATF F-1

Mazda ATF N-1, Mazda ATF 3317, MINI COOPER T-IV, Mitsubishi,Diaqueen SK, itsubishi, Diaqueen SP II, Mitsubishi, Diaqueen SP, III Mitsubishi Diaqueen SP IV, Mitsubishi Diaqueen AW, Mitsubishi Diaqueen J2, Mitsubishi Diaqueen J3, Mitsubishi Diaqueen ATF PA, Nissan Matic Fluid C, D, J, K and S, Porsche T-IV (JWS 3309), Saab T-IV (JWS 3309), Saab 93 165 147, Saturn T-IV (JWS 3309), Scion (all vehicles), Subaru ATF, ATF 5AT, ATF HP,Subaru Dexron®-II, Suzuki ATF 3314, Suzuki AT OIL 5D06, Suzuki ATF 2326, Suzuki ATF 2384K, Suzuki ATF JWS 3309, Suzuki ATF 3317, Texaco N402, Toyota ATF T-III, T-IV, Toyota ATF D-II,D-III, Toyota ATF WS	

Revision Number

15.12.2025 / REV07